

Southworth-Milton, Inc.
 100 Quarry Drive
 Milford, MA 01757
 USA



Enercon Engineering, Inc.
 201 Altorfer Lane
 East Peoria, IL 61611
 USA

Telephone 508-634-3400
 Fax
 Tax registration number

Invoice

Number 113685
 Date 8/21/2020
 Page Page 1 of 3
 Purchase order [PO00901479](#)
 Internal number APIIN1091679
 Payment Net 30

Item number	Description	Quantity	Unit	Unit price	Discount percent	Discount	Amount
INV60000	Container Refurbishment Quantity : 1.00 Warehouse : ENERCON	1.00	pc	21,340.71	0.00	0.00	21,340.71
INV60000	Engine Removal / Reinstallation Quantity : 1.00 Warehouse : ENERCON	1.00	pc	10,098.61	0.00	0.00	10,098.61
INV60000	Reconditioning of Fuel Tank Quantity : 1.00 Warehouse : ENERCON	1.00	pc	6,398.72	0.00	0.00	6,398.72
INV60000	Radiator Refurbish Quantity : 1.00 Warehouse : ENERCON	1.00	pc	78,230.21	0.00	0.00	78,230.21
INV60000	Replace Flex Hoses Quantity : 1.00 Warehouse : ENERCON	1.00	pc	1,274.79	0.00	0.00	1,274.79
INV60000	Controls Package Upgrade to 4.4 Quantity : 1.00 Warehouse : ENERCON	1.00	pc	65,427.26	0.00	0.00	65,427.26
INV60000	Auxiliary Electrical Package Upgrade Quantity : 1.00 Warehouse : ENERCON	1.00	pc	9,248.08	0.00	0.00	9,248.08
INV60000	Electrical Removal / Reinstallation (for fuel tank removal) Quantity : 1.00 Warehouse : ENERCON	1.00	pc	1,063.01	0.00	0.00	1,063.01
INV60000	Exhaust System Replacement Quantity : 1.00 Warehouse : ENERCON	1.00	pc	5,085.99	0.00	0.00	5,085.99
INV60000	4 Hr Load Test Quantity : 1.00 Warehouse : ENERCON	1.00	pc	7,208.82	0.00	0.00	7,208.82

Southworth-Milton, Inc.
 100 Quarry Drive
 Milford, MA 01757
 USA



Enercon Engineering, Inc.
 201 Altorfer Lane
 East Peoria, IL 61611
 USA

Telephone 508-634-3400
 Fax
 Tax registration number

Invoice

Number 113685
 Date 8/21/2020
 Page Page 2 of 3
 Purchase order [PO00901479](#)
 Internal number APIIN1091679
 Payment Net 30

Item number	Description	Quantity	Unit	Unit price	Discount percent	Discount	Amount
INV60000	Adder - Secure Radiator Fan Blade Counterbalance Quantity : 1.00 Warehouse : ENERCON	1.00	pc	226.72	0.00	0.00	226.72
INV60000	Adder - Wash and repaint genset, remove and reinstall generator for rebuild Quantity : 1.00 Warehouse : ENERCON	1.00	pc	7,330.27	0.00	0.00	7,330.27
INV60000	Adder - Extra work to exhaust system due to removal of old system Quantity : 1.00 Warehouse : ENERCON	1.00	pc	6,170.58	0.00	0.00	6,170.58
INV60000	Adder - Fuel system, add gauges to racors, install pump Quantity : 1.00 Warehouse : ENERCON	1.00	pc	2,251.24	0.00	0.00	2,251.24
INV60000	Adder - additional internal / external container work, wipe clean interior walls, patch panelwalls, secure bottom sheets Quantity : 1.00 Warehouse : ENERCON	1.00	pc	2,292.22	0.00	0.00	2,292.22
INV60000	Adder - Investigate and repair floor under rear isolators - T&M Quantity : 1.00 Warehouse : ENERCON	1.00	pc	2,307.87	0.00	0.00	2,307.87

