

Inspection completed of 3516 caterpillar engine ESN: TTD00415. Unit looks like new on borescope inspection and complete on the outside of the engine. See attached pictures of #1cylinder. All cylinders look the same. No issues or concerns reported of engine condition following the completed inspection.

